

SN 10 / 522434 Atty's 23198
REPLACEMENT SHEET (1 - 9)




Fig. 1




Fig. 2

SN 10 / 522434 Atty's 23198
REPLACEMENT SHEET (3 - 9)




Fig. 3




Fig. 4




Fig. 5




Fig. 6

SN 10 / 522434 Atty's 23198
REPLACEMENT SHEET (7 - 9)




Fig. 7




Fig. 8

THE CONSTRICION OF RESISTANCE LIQUID BY THE FLOAT VARIES THE VOLTAGE DROP AT MIDDLE CONDUCTOR CORRESPONDING TO TILT




Fig. 9a




Fig. 9b